


134,234 235,236,237 238 239 104 240 241 242 79 243 244 245 56 246 29 247 MALLARD LAKE 11




Environment Branch  
Resources/Environment Group

Waterhen Area (73K)  
CROSS SECTION  
L-L'

11 Testhole number

Location of testhole/well  
indicates top and bottom

This document may not be copied without the consent of the authors. However, copies may be made, except for resale, for personal or internal use of the client, provided the original publication is cited where applicable.



LIMITATIONS:  
Except at testhole sites where geological logs are available the geologic contacts are inferred and represent geologic models that are believed to best fit the information.

Accompanies SRC report R-1510-6-E-97  
Drawing name: 73k\_L.dwg  
Date: July 1997